Approved For Belease 2002/88/15 PC/A-ROPF4B000326/2000030230005-8 SECRET 25X1A ACTION 20 NOV \$5 3 3 3 2 4 REPRODUCTION PROHIBITED 25X1A ACTION 2	FORM 12-67 ²⁸²⁰	`	Ret	con to:	
ACTION 1	The state of the s	SECRET	Ð₽F4B0083€R0003		
25X1A 2	2 0 Nov 69 8 3 3 2 4	REPRODUCTION PROHI	BITED	CU NOVE ; j	Û
25X1A 25X1A 25X1A 25X1A 26 25X1A 26 25X1A 27 NNNS E C R E T 200856Z NOV 69 CITE DIDEALIST D/M-3 REF: ACCIDENT REPORT OF U-3A, 58-2186 1. REQUEST CESSNA FACTORY BE QUERIED FOR FOLLOWING INFO: 4. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUPPORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). 8. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N 2841200-13, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T					
NNNS E C R E T 200856Z NOV 69 CITE DEALIST D/M-3 REF: ACCIDENT REPORT OF U-3A, 58-2186 1. REQUEST CESSNA FACTORY BE QUERIED FOR FOLLOWING INFO: A. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUP- PORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N 3841200-13, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	3	8 Idea	13	18	
IDEALIST D/M-3 REF: ACCIDENT REPORT OF U-3A, 58-2186 1. REQUEST CESSNA FACTORY BE QUERIED FOR FOLLOWING INFO: A. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUP- PORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N 9841200-13, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	5	SA 10 RB			
REF: ACCIDENT REPORT OF U-3A, 58-2186 1. REQUEST CESSNA FACTORY BE QUERIED FOR FOLLOWING INFO: A. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUPPORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N ### ### ### ### ### ### ### ### ### #	NNNS E C R E T 200856Z	VOV 69 CITE			25X
REF: ACCIDENT REPORT OF U-3A, 58-2186 1. REQUEST CESSNA FACTORY BE QUERIED FOR FOLLOWING INFO: A. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUPPORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N ### ### ### ### ### ### ### ### ### #		v.			
1. REQUEST CESSNA FACTORY BE QUERIED FOR FOLLOWING INFO: 4. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUPPORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). 8. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N Ø841200-18, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	IDEALIST D/M-3				
A. MAXIMUM ALLOWABLE SIDEPLAY FOR NOSE WHEEL SUP- PORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N 9841200-13, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	REF: ACCIDENT REPORT OF	F U-3A, 58-2186		-	
PORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N Ø841200-18, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	1. REQUEST CESSNA FA	ACTORY BE QUERIED FO	OR FOLLOWING I	NFO:	
PORT MOUNT WITH LOWER SHOCK STRUT IN EXTENDED POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N ### ### ### ### ### ### ### ### ### #	A. MAXIMUM ALLOWAE	BLE SIDEPLAY FOR NOS	SE WHEEL SUP-		
POSITION. (SEE TAB Z, FIGURE 2 OF REF). B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N 0841200-13, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T		H LOWER SHOCK STRUT	IN EXTENDED		
B. MAXIMUM ALLOWABLE CLEARANCE BETWEEN BEARING, P/N ### ### ### ### ### ### ### ### ### #					
### 1200-13, (ON TOP OF LOWER SHOCK STRUT) AND INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T		•		/ A1	
INSIDE WALL OF UPPER SHOCK STUT. (SEE TAB Z, FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTION OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T				1V	
FIGURE 3 AND 4 OF REF). 2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTION OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	•				
2. ABOVE INFO NOT IN MANUALS. LAC HAS QUERIED CESSNA DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTEON OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	INSIDE WALL OF	UPPER SHOCK STUT.	(SEE TAB Z,	×	•
DEALERS AND OVERHAUL FACILITIES IN LOS ANGELES FOR INFO BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTION OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	FIGURE 3 AND 4	OF REF).			
BUT WITH NEGATIVE RESULTS. 3. RECOMMEND MAKE ONE TIME INSPECTION OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	2. ABOVE INFO NOT I	N MANUALS. LAC HAS	QUERIED CESS	NΑ	
3. RECOMMEND MAKE ONE TIME INSPECTION OF BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	DEALERS AND OVERHAUL FA	CILITIES IN LOS ANGE	ELES FOR INFO	·	
BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	BUT WITH NEGATIVE RESULT	TS•			
BEARINGS IN NOSE GEAR ASSEMBLY OF THEIR U-3 A'S IN THE EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T	3. RECOMMEND	MAKE ONE TIME INS	SPEC SON OF		
EVENT THEY HAVE NOT RECENTLY BEEN INSPECTED. S E C R E T					5X1A
SECRET					
		EWILI DEEW INSPECTED	J•		
BT	SECRET				
	ВТ				